




REAC/TS

Radiation Emergency
Assistance Center/Training Site

Putting on Protective Clothing (Donning)

- 1 Shoe Covers.
- 2 Coveralls or Isolation Gown: At minimum, fully cover torso from neck to knees, arms to ends of wrists. Fasten or secure appropriately.
- 3 First set of gloves underneath cuff of coveralls or gown.
- 4 Tape sleeves and trouser cuffs (as applicable). Tape any other potential areas of contaminant entry, such as an uncovered zipper.
- 5 Face Mask: Secure ties or elastic band. Fit flexible band to bridge of nose and secure below chin.
- 6 Head Covering.
- 7 Face Shield or Goggles.
- 8 Second set of gloves. Extend to cover wrist of coveralls or isolation gown.
- 9 Identifying Information: Name and role on front and back of protective wear.
- 10 Dosimeter (if available).



OAK RIDGE INSTITUTE
FOR SCIENCE AND EDUCATION
Shaping the Future of Science